


**Bathroom in this RV was fiberglass panel covered with bright yellow, orange, and green flowers that screamed “the 70’s”. Door was covered with vinyl wallpaper that was removed before coating with Thermo-shield Stucco.**



The image shows the interior of a vehicle, likely a truck or bus, focusing on a door area. On the left, a dark wood-grain door panel is visible. A silver door handle is mounted on a light-colored, possibly white or light grey, wall. To the right of the handle is a rectangular window with a dark frame, looking out onto a bright, overexposed exterior. The overall lighting is somewhat dim, with the primary light source being the window. The text is overlaid in the center-right of the image.

**Walls, door  
and ceiling  
were all  
given new  
looks and  
lasting  
durability.**



**Everyone  
loves the way  
the bathroom  
looks with the  
soft sand  
plaster  
texture.**