

Sunrise on Lake Powell finds “The Crew” still sleeping. The sun, however, is a powerful alarm clock. It will soon drive those who slumber on top of the boat to awaken with the immediate, developing heat the sunlight brings.





Mug shot of one of the rough and tumble “Crew” at Camp Thermo Lake Powell 08. As you can see from this example, these are some pretty tough characters.

**Could not even get this
“crazy” to slow down for a
picture.**




And just one look at these guys says it all.... TROUBLE. On this trip we had about 20 people, all out for a week of fun and sun at beautiful Lake Powell.



**Sunrise finds the “wild things” in their only peaceful state: sleeping!
Take this extreme use and multiply it by 24 (the number of weeks the
Jobsite is in use each summer) and you get some idea of the wear and
tear this Thermo-shield Roof goes through each year.**



Bow to stern Thermo-shield coverage on the roof deck keeps temperature inside way down. And it stays cool enough to walk on all summer long, even on those 115 degree days! (which occur all summer long at Lake Powell)



After 4 seasons of constant summer use and 4 years extreme winter weathering, the Thermo-shield Roof System looks great. And there has not been one drip of water inside the boat. (a problem every year with the old elastomeric roof system)

